A. Krödel
J. C. Rehmet
C. Hamburger

Spinal cord compression caused by the rod of a Harrington instrumentation device: a late complication in scoliosis surgery

Received: 5 July 1996
Revised: 8 November 1996
Accepted: 9 December 1996

A. Krödel (✉) · J. C. Rehmet
Orthopaedic Department,
Ludwig Maximilians University Munich,
Klinikum Grosshadern,
Marchioninistrasse 15,
D-81377 Munich, Germany
Fax +49-89-7095 2618

C. Hamburger
Neurosurgical Department,
Ludwig Maximilians University Munich,
Klinikum Grosshadern, Munich, Germany

Abstract We report a unique complication caused by the rod of a Harrington instrumentation device, which resulted in spinal stenosis and myelopathy. A literature review revealed no previous causes of direct spinal cord impingement caused by the rod of a Harrington device. In this case, years after the initial operation, the rod penetrated the lamina at the junction between a thoracic

and a lumbar curve, causing spinal stenosis and myelopathy. We conclude that regular control of the position of the device and awareness of possible late neurological complications are necessary to identify such complications as early as possible.

Key words Scoliosis, surgery · Spinal fusion, complications · Spinal fusion, instrumentation

Introduction

Operative treatment in idiopathic scoliosis, performed for more than four decades using different surgical techniques, yields, in most cases, satisfactory results. The rate of complications is acceptable compared to the severity of the problem. Acute neurological problems, most of them requiring removal of hardware, are the most important early complications. Predominant among the secondary problems after discharge of the patients are pseudarthrosis and fracture of the instrumentation. Late occurrence of neural lesion, without trauma, years after surgery, remains exceptional [1–14, 16, 17].

We describe a case of myelopathy caused by a Harrington rod that penetrated the lamina and indented the spinal cord. The patient had undergone posterior spinal fusion with Harrington instrumentation 7 years previously.

Case report

A 55-year-old woman presented with a history of Albee fusion for scoliosis at the age of 19 years. Twenty-nine years later, she underwent Harrington instrumentation with a distraction rod and

compression system from the T4 to the L4 vertebra because of a combined thoracolumbar curve. This second operation had to be carried out because of increasing lumbar pain and loss of correction. For this purpose, lumbar transpedicular instrumentation and fusion was performed, but no laminectomy.

After Harrington rod instrumentation in 1988 the patient was never painfree, but until 1994 the pain was limited to the thoracic spine region without radiation. At this time, the patient could provoke muscle fibrillation in the left thigh with sudden onset by certain movements in the thoracolumbar region. A few months later, these symptoms changed into severe pain in both lower limbs accompanied by hypoesthesia and weakness. In February 1995, increasing urge-incontinence and impaired balance was noticed by the woman.

On admission, she presented with spastic-atactic gait with a fall tendency to the left. Hypoesthesia was present below the L1 level. She had mild weakness of the psoas and quadriceps muscles, knee and ankle reflexes were hyperactive bilaterally. Babinski reflex was positive on the left side, straight-leg raising was pain free on both sides.

Myelography showed a remarkable filling defect at the T11–T12 level, where the rod had penetrated the T11–T12 laminae (Fig. 1). Obvious findings on CT scans were rod contact and consequent compression of the spinal cord (Fig. 2). On the basis of these findings, removal of the distal part of the Harrington rod was performed. Intraoperatively, the rod was found to be mobile, but a stable bony fusion was observed. After removal of the rod below the level of T10, clear signs of laminar pressure atrophy over a distance of 5 cm appeared. The spinal cord showed fibrotic, cicatricial

changes. Decompression of the involved spinal cord was performed. Only this part of the fusion was examined for pseudarthrosis. As the fusion seemed to be solid, no regrant or new instrumentation was performed. Histological examination of scar tissue revealed fibrous tissue layers.

Postoperatively, the patient regained neural function. On discharge, 2 weeks after surgery, she was able to walk without help. She felt only a little pain in the scar region. Bladder and bowel function were normal. Hypoesthesia, hyperreflexivity, muscle weakness, and ataxia of gait had clearly receded. The radiographs showed that the fusion was solid without any increase in the curve beyond the preoperative findings.

Fig. 1 A 55-year-old woman, 6 years after Harrington instrumentation of idiopathic scoliosis. Myelograph showing complete block of contrast media at the T11-T12 level (*arrow*)

Fig. 2 CT scan: direct contact between the rod and the spinal cord can be seen

Discussion

This is the first case of this type of late neurological complication after Harrington rod instrumentation, as far as literature shows. Most reported neurological complications occur immediately after surgery, particularly after use of sublaminar wiring [7, 10, 13, 14]. The reported complications were caused by the sublaminar wiring, the hooks, pseudarthrosis, late infection, or spinal stenosis distal to the fusion, but not by the rod itself. Single case studies of neurological affections appearing years after surgery, such as, for example, sciatic nerve compression by encapsulated hematoma, root compression by a lumbar hook, or neural affections caused by rod breakage or hook displacement can be found [1, 3, 5, 7, 10, 14, 16]. It is likely that our patient initially had a junctional thoracolumbar kyphosis, which was pushed forward by forceful insertion of a Harrington rod into the cranial and caudal hooks. Direct pressure on the laminae, probably reinforced by micromotion of the rod, then led to atrophy of the laminae, migration of the rod, and spinal cord compression over the years (Fig. 3). Given the fact that the Harrington rod was initially inserted with a certain tension in the area of junctional thoracolumbar kyphosis, this tension was probably lost while penetrating the lamina. So micromotion of the rod in the event of stable fusion could be the cause of the patient's symptoms. Additional support for this theory is given by the fact of pain intensification by certain voluntary movements, which implies some form of instability. Since, during surgery, only a part of the fusion mass was explored, the possibility of a pseudarthrosis in other parts of the fusion cannot be excluded.

To diminish the risk of protrusion of the rod into the spinal canal, forces acting on bony structures should be distributed as widely as possible. Therefore, multisegmental instrumentation systems should be used in dorsal scoliosis surgery instead of a two-point fixation, such as

Fig. 3 Myelograph: lateral view of the thoracic spine shows direct contact between the rod and the spinal cord (*arrow*)

in Harrington instrumentation [15]. Using a Harrington rod in kyphosis, as described here, has to be seen as an additional risk factor for provocation of this complication in spine surgery.

In addition, patients should be followed carefully after fusion for scoliosis to detect complications like this one as early as possible to avoid persisting neural affections.

References

1. Been HD, Kalkman CJ, Traast HS, Ongerboer de Visser BW (1994) Neurologic injury after insertion of laminar hooks during Cotrel-Dubousset instrumentation. *Spine* 19: 1402–1405
2. Bernard TN, Johnston CE, Roberts JM, Burke SW (1983) Late complications due to wire breakage in segmental spinal instrumentation. *J Bone Joint Surg [Am]* 65: 1339–1345
3. Court-Brown CM, McMaster MJ (1982) Pseudarthrosis: a late cause of paraparesis after scoliosis surgery. *J Bone Joint Surg [Am]* 64: 1246–1248
4. Curtis RS, Dickson JH, Harrington PR, Wendell DE (1979) Results of Harrington instrumentation in the treatment for severe scoliosis. *Clin Orthop* 144: 128–134
5. Dove J (1988) Segmental wiring for spinal deformity. A morbidity report. *Spine* 14: 229–231
6. Eismont FJ, Simeone FA (1981) Bone overgrowth (hypertrophy) as a cause of late paraparesis after scoliosis fusion. *J Bone Joint Surgery [Am]* 63: 1016–1019
7. Guillemin F, Czorny A, Pouewl J (1991) Sciatic nerve compression by hematoma: case report of a late complication of Harrington's operation. *Spine* 16: 237–239
8. Hales DD, Dawson EG, Delamarter R (1989) Late neurological complications of Harrington-Rod instrumentation. *J Bone Joint Surg [Am]* 71: 1053–1057
9. Johnston CE, Happel LT, Norris R, Burke SW, King AG, Roberts JM (1986) Delayed paraplegia complicating sublaminar segmental spinal instrumentation. *J Bone Joint Surg [Am]* 68: 556–563
10. Kornberg M, Herndon WA, Rehtine GR (1985) Lumbar nerve root compression at the site of hook insertion: late complication of Harrington rod instrumentation for scoliosis. *Spine* 10: 853–855
11. MacEwen GD, Bunnell WP, Sriram K (1975) Acute neurological complications in the treatment of scoliosis. *J Bone Joint Surg [Am]* 57: 404–408
12. Michel CR, Lalain JJ (1985) Late results of Harrington's operation. *Spine* 10: 414–419
13. Moskowitz A, Moe JH, Winter RB, Binner H (1980) Long-term follow-up of scoliosis fusion. *J Bone Joint Surg [Am]* 62: 364–375
14. Savini R, Di Silvestre M, Gargiulo G (1990) Late paraparesis due to pseudarthrosis after posterior spinal fusion. *J Spine Disord* 3: 427–432
15. Schlenszka D, Poussa M, Muschik M (1993) Operative treatment of adolescent idiopathic thoracic scoliosis. *Clin Orthop* 297: 155–160
16. Thompson GH, Wilber RG, Shaffer JW, Scoles PV, Nash CL (1985) Segmental spinal instrumentation in idiopathic scoliosis. A preliminary report. *Spine* 10: 623–630
17. Wilber RG, Thompson GH, Shaffer JW, Brown RH, Nash CL (1984) Postoperative neurological deficits in segmental spinal instrumentation. *J Bone Joint Surg [Am]* 66: 1178–1187