CASE REPORT

Positional convulsant syncope in a pacemaker patient following insulation break of the right ventricular lead

Mehdi Ben Lassoued,¹ Makram Baatour,¹ Abdeddayem Haggui,² Khaled Lamine¹

¹Emergency Department, Military Hospital of Tunis, Faculty of Medicine, University of Tunis El Manar, Tunis, Tunisia

²Cardiology Department, Military Hospital of Tunis, Faculty of Medicine, University of Tunis El Manar, Tunis, Tunisia

Correspondence to
Dr Mehdi Ben Lassoued,
mehdi.benlassoued@gmail.com

Accepted 8 April 2014

SUMMARY

In spite of the advances made in the technology of pacemakers which resulted in a decrease in the incidence of pacemaker lead fracture, the latter remains a potential complication of implanted pacemakers manufactured in the early days. In this report, we present a case of fracture of the unipolar electrode diagnosed by an emergency physician in a patient on a pacemaker for 10 years who presented to the emergency department with positional convulsant syncope.

spite of the advances made in the technology of pacemakers which resulted in a decrease in the incidence of pacemaker lead fracture,¹ the latter remains a feared complication over time in old pacemakers. Here is a case of this rare and puzzling clinical situation leading to this dysfunction.

CASE PRESENTATION

This is the case of a 73-year-old man on a dual-chamber pacemaker implanted 10 years ago for a high-grade atrioventricular block, who presented to our emergency department for repeated convulsant syncope during the previous 6 h. The convulsions occurred following the slightest change in the head

BACKGROUND

Convulsant syncope occurring in a patient on a pacemaker are usually due to a low cardiac output resulting from a dysfunction of the pacemaker. In

Figure 1 Critical monitoring: severe bradycardia with non-conducted atrial spikes followed by asystole.

Figure 2 Critical monitoring: spontaneous resumption of a ventricular escape rhythm (wide QRS) at 60 bpm with atrial spikes.

To cite: Ben Lassoued M, Baatour M, Haggui A, *et al.* *BMJ Case Rep* Published online: [please include Day Month Year] doi:10.1136/bcr-2013-202948

Figure 3 X-ray film performed at the patient's bed: a fractured ventricular lead at the level of the right thoracic outlet (left-handed patient).

or trunk positions of the patient and on raising his right upper limb.

Physical examination on admission yielded the following findings: absence of fever, Glasgow Coma Scale (GCS) at 15/15, blood pressure 130/80 mm Hg, regular pulse 68 bpm and blood glucose level 1.2 g/L. Cardiopulmonary auscultation was normal and so was the rest of the physical examination.

The patient had a convulsant syncope in the emergency department on raising his right upper limb. Monitoring during the critical phase showed extreme bradycardia with non-conducted atrial spikes followed by a prolonged asystole phase (7–8 s; [figure 1](#)). The attack resolved rapidly with a spontaneous resumption of ventricular escape rhythm (wide QRS) at 60 bpm ([figure 2](#)).

A dysfunction of the pacemaker due to a fracture in the lead was suspected.

INVESTIGATIONS

Posterior view on chest X-ray film performed at the patient's bed showed a fractured ventricular lead at the level of the right thoracic outlet (left-handed patient; [figure 3](#)).

Figure 4 Chest X-ray after implantation of a new pacemaker on the left side.

TREATMENT

Management consisted of an emergency implantation of a new pacemaker on the contralateral side ([figure 4](#)).

OUTCOME AND FOLLOW-UP

The course was uneventful.

DISCUSSION

Right ventricular lead fracture is a feared complication of dysfunction of a pacemaker (1–4%).^{2,3} Most fractures occur in the zone very near the subclavian venous entry site following compression of the lead between the clavicle and the first rib or entrapment of the lead by soft tissue in the costoclavicular zone.^{4,5}

Inhibition of a pacemaker is related to overdetection of the right ventricle lead as a result of insulation break. In our patient, the changes in the positions lead to pulling both ends of the insulation break thus stripping the male lead which is in contact with the pectoral muscle. The pacemaker considers the myopotentials as a spontaneous ventricular activity and this results in an asystole. The pacemaker does not make any difference between cardiac activity and muscular activity.

Lead fracture may be detected by the emergency physician by an ECG showing no evidence of pacemaker activity as is shown in [figure 1](#), or by chest X-ray revealing a pacemaker insulation break that is clearly visible near the clavicle as is shown in [figure 3](#).⁶ Undersensing or oversensing of the lead noise may also indicate lead fractures.⁷ Moreover, intermittent pauses in the conduction of the electrical impulse may suggest a partial lead fracture that is invisible in the radiographic image.⁸ Definite diagnosis is made possible by a control of the pacemaker by telemetry which confirms the important variation in the lead impedance mainly in adduction and abduction of the homolateral upper limb.

Patients on pacemakers should avoid excessive movements of the upper limbs and direct compression of the chest wall.⁴ Our patient was unfortunately dependent on the pacemaker. That is why he had a prolonged asystole (7–8 s) phase followed by a spontaneous resumption of a ventricular escape rhythm immediately after adduction of the right upper limb. The ventricular escape rhythm can be explained by an increased intrinsic secretion of adrenaline provoked by the syncope itself. The spikes seen on [figures 1](#) and [2](#) are atrial spikes in keeping with a faulty atrial detection.

Management consisted of replacing this old pacemaker that was implanted 10 years ago. Non-functional leads were kept in place, for their extraction requires specific techniques using mechanical dilators or laser and may be complicated by a vascular rupture, pneumothorax, cardiac perforation, tamponade and even death of the patient.⁹ Extraction is mandatory in case of contaminated equipment. As for unnecessary leads, their extraction is debateable when the number of leads is more than five.⁹

Learning points

- ▶ Fracture of the right ventricular lead is a feared complication of dysfunction of a pacemaker (1–4%).
- ▶ This aetiology should be considered by the emergency physician whenever the patient presents severe symptoms and signs caused by low cardiac output occurring as a result of the slightest change in the patient's position.
- ▶ Treatment consists of urgent implantation of a new device.

Contributors MBL and MB were involved in the clinical diagnosis of the patient and edited the abstract. AH implanted the new pacemaker. KL monitored the case report.

Competing interests None.

Patient consent Obtained.

Provenance and peer review Not commissioned; externally peer reviewed.

REFERENCES

- 1 Saha A, Tan J, Prendergast B. Pacemaker lead fracture. *Heart* 2003;89:783.
- 2 Alt E, Volker R, Blomer H. Lead fracture in pacemaker patients. *Thorac Cardiovasc Surg* 1987;35:101–4.
- 3 Magney JE, Flynn DM, Parsons JA, *et al.* Anatomical mechanisms explaining damage to pacemaker leads, defibrillator leads, and failure of central venous catheters adjacent to the sternoclavicular joint. *Pacing Clin Electrophysiol* 1993;16:445–57.
- 4 Deering JA, Pederson DN. Pacemaker lead fracture associated with weightlifting: a report of two cases. *Mil Med* 1993;158:833–4.
- 5 Shu-Hsuan C, Che-Kim T, Shih-Huang L. Fracture of a pacemaker lead. *CMAJ* 2009;181:769.
- 6 Varriale P, Kwa RP, Vyas P. The 'lead tug' sign for the diagnosis of early and unapparent lead fracture. *Chest* 1982;82:787–8.
- 7 Chan TC, Cardall TY. Electronic pacemakers. *Emerg Med Clin North Am* 2006;24:179–94.
- 8 Hakan A, Sercan O, Ugur K, *et al.* Incomplete pacemaker lead fracture revealed by superficial maneuvers. *Arch Turk Soc Cardiol* 2010;38:363–5.
- 9 Wilkoff BL, Love CJ, Byrd CL, *et al.* Transvenous lead extraction: Heart Rhythm Society expert consensus on facilities, training, indications, and patient management. *Heart Rhythm* 2009;6:1085–104.

Copyright 2014 BMJ Publishing Group. All rights reserved. For permission to reuse any of this content visit <http://group.bmj.com/group/rights-licensing/permissions>.
BMJ Case Report Fellows may re-use this article for personal use and teaching without any further permission.

Become a Fellow of BMJ Case Reports today and you can:

- Submit as many cases as you like
- Enjoy fast sympathetic peer review and rapid publication of accepted articles
- Access all the published articles
- Re-use any of the published material for personal use and teaching without further permission

For information on Institutional Fellowships contact consortiasales@bmjgroup.com

Visit casereports.bmj.com for more articles like this and to become a Fellow