Recurrent collapses following permanent pacemaker implantation

M. N. Attar · F. Z. Ahmed · R. K. Moore

Published online: 8 October 2011
© Springer Media / Bohn Stafleu van Loghum 2011

A 23-year-old lady presented with collapses associated with transient loss of consciousness. She had undergone permanent pacemaker implantation five months earlier for intermittent complete heart block.

An echocardiogram showed that the ventricular lead crossed the interatrial septum into left ventricle (LV) (Fig. 1a). Pacing check with a magnet revealed a right bundle branch block (RBBB) pattern indicating that left

Fig. 1 **a** Transthoracic echocardiogram. 1. PLAX-parasternal long axis, solid arrow-ventricular lead, LA- left atrium, LV- left ventricle, IVS- interventricular septum, RV-right ventricle, MV-mitral valve, AO- aorta. 2. PSAX-parasternal short axis, solid arrow- ventricular lead, IAS-interatrial septum. 3. A-4 C-apical 4

chamber, broken arrow-ventricular lead crossing interatrial septum and solid arrow- tip of the ventricular lead in left ventricle. **b** Lateral chest X-Ray showing displaced atrial lead and posterior location of ventricular lead indicating malposition into left ventricle

M. N. Attar · F. Z. Ahmed · R. K. Moore
Department of Cardiology, Lancashire Cardiac Centre, Blackpool
Victoria Hospital,
Blackpool, Lancashire, UK FY3 8NR

M. N. Attar (✉)
28, St.Francis Close Preston,
Lancashire, UK PR2 9WJ
e-mail: nadattar@hotmail.com

ventricle was being paced. Lateral chest X-ray (CXR) showed lead malposition (Fig. 1b).

Following the first procedure she only had a postero-anterior CXR showing satisfactory lead position, which alone is inadequate to accurately confirm lead positions. ECG, which could have alerted to the possibility of pacing the LV, was not performed.

Lead malposition is a rare complication of pacemaker implantation. Diagnosis of left ventricular lead malposi-

tion requires a high index of suspicion. A 12-lead ECG and a lateral CXR following pacemaker implantation can be diagnostic [1]. A 12-lead ECG in pace mode and in case of RBBB pattern echocardiogram for precise lead position has been recommended [2].

Funding Nil

Conflict of interest Nil

References

1. Van Gelder BM, Bracke FA, Oto A, et al. Diagnosis and management of inadvertently placed pacing and ICD leads in the left ventricle: a multicenter experience and review of the literature. *Pacing Clin Electrophysiol.* 2000;23(5):877. review.
2. Zielińska M, Kaczmarek K, Koniarek W, et al. The significance of electrocardiogram in the estimation of correct lead position in patients with permanent ventricular pacing. *Wiad Lek.* 2006; 59(7–8):580–4.